




Doc. No.: 115.TM.001		Grob Aircraft AG															
Chapter: 2																	
Type: G 115	LBA-TCDS No.: 1078																
		Service Bulletins (issued / in preparation)														Status: 09. May 2012	
SB-No.	ÄM No.	Subject	Date of issue	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA	Major Change	Minor Change	Remarks	
1078-1		Installation of additional equipment, revision of Flight manual	24.06.87	X												German language	
1078-2/1		Installation of a spring device between aileron and rudder	15.06.88	X													
1078-3		Special equipment for export to the Netherlands	15.06.88	X													
1078-4		Revision 3 of the Flight Manual G 115 (German Issue)	01.07.88	X												German language	
1078-5		Special equipment for export to the USA	16.12.88	X													
1078-6		Approval of installation of a primer system	20.12.88	X													
1078-7		Authorized installation of the SENSENICH prop 72CK56-2-53	16.12.88	X													
1078-8		Exchange of the bowden cables...	22.05.89	X													
1078-9		Extension of operation limits, new edition of FM , inst.	24.10.89	X													
1078-10		Design standard and special equipment for export to UK	28.04.92	X	X												
1078-12/1		Cracks on main landing gear axles	04.07.90	X	X												
1078-13		Modification of the main landing gear	07.06.91	X	X												
1078-14		Replacement of both aileron control rods no.1	05.06.90	X	X												
1078-15		Permitted modifications of the nose landing gear	06.05.91	X													
1078-16		Replacement of fuel hose on the firewall	18.09.90	X	X												
1078-17		Check of the PA bushes in the steering damper	19.11.90		X												
1078-18		Replacement of bonding lead assembly VV5	16.05.91		X												
1078-19		Permitted modifications of the nose landing gear	03.07.91	X	X												
1078-20		Installation of a rudder trim plate	23.07.91	X	X												
1078-21		Installation of maintenance free fuel lines	02.12.91	X	X												
1078-22		Installation of an Emergency Locator Transmitter	09.09.91	X	X											France only	
1078-23		Installation of an additional rudder stop	16.10.91	X	X												
1078-24		Inspection of the flap hinges	23.06.92		X												
1078-25		Revision of the Flight Manuals G 115/ G 115A	13.08.92	X	X												
1078-27/2		Modification of the G115/115A to the G115B standard	21.04.93	X	X												
1078-28		Modification to the wing flap hinges	29.03.93		X												
1078-29/2		Elevator lever exchange	12.08.93	X	X	X											
1078-30		Inspection or modification of elevator and elevator trim.	13.08.93	X	X	X											
1078-31		Installation of a GRP nose wheel fork	22.09.93	X	X	X											
1078-32		Installation of equipment for VFR night, CVFR,...	03.11.94				X	X	X	X							
1078-33		Modification of the nose wheel support, Installation ...	18.04.94				X		X	X							
1078-34		Reduction of the never exceed speed vne	29.04.94							X							


X = applicable

Doc. No.: 115.TM.001		Grob Aircraft AG															
Chapter: 2		Service Bulletins											Status: 09. May 2012				
Type: G 115		(issued / in preparation)															
LBA-TCDS No.: 1078																	
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks	
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA				
1078-35		Improvements and modifications during series production	06.05.94				X		X	X							
1078-36/2		Improvements and modifications during series production	01.06.94				X		X	X							
1078-37		Revision of the Flight Manual G 115D2	03.06.94							X							
1078-38		Stiffening of LH and RH seat shell, Installation of a..	16.06.94				X		X	X							
1078-39		Revision of the Flight Man. G 115D2 (German issue)	20.06.94							X							German language
1078-40		New issue Flight Manual G 115C (German issue)	01.05.94				X										German language
1078-41		Modification to the canopy	06.07.94				X	X	X	X							
1078-42		Revision of the Flight Manual G 115C	11.07.94				X										
1078-43		Revision of the Flight Manuals G 115C2 G 115D2	18.07.94						X		X						
1078-44		Revision of the Flight Manual G 115D	25.07.94							X							
1078-45		Modifications during series production	01.08.94				X	X	X	X							
1078-46		New issue Flight Manual G 115D (German issue)	01.06.94							X							German language
1078-47		Revision of the Flight Manuals, new issue FM	11.10.94				X	X	X	X							
1078-48		Revision of the Maintenance Manuals	17.10.94	X	X	X											
1078-49		Inspection and exchange of the carburetor temp. sens.	05.12.94	X	X	X	X	X									
1078-50		Revision FM, Installation of equipment for IFR operation	12.12.94				X	X	X	X							
1078-51		Inspection and reinforcement of the main undercarriage	18.01.95				X	X	X	X							
1078-52/2		Repair of the front pedal ribs, reinforced pedal levers	31.05.96				X	X	X	X							
1078-54		Modifications and improvements to the G115C/D	01.09.95				X	X	X	X							
1078-55		Use of the G115C for limited acrobatic operation					X										
1078-56		Installation of a LIESE muffler to G115 with SENSENICH prop	12.12.95	X	X												
1078-57		Replacement of the engine instruments	20.12.95				X	X	X	X							
1078-58		Modifications and improvements to the G115C/D	27.01.96				X	X	X	X							
1078-59/3		Validation of the never exceed speed / acro maneuvers	24.10.96				X	X	X	X							
1078-60		Replacement of the airplane identification plate	13.02.96				X										
1078-61		Reinforcement of the main undercarriage attachment	20.02.96				X	X	X	X							
1078-62		Modification of the horizontal stabilizer attachment	05.12.96				X	X	X	X							
1078-63		Optional modification of the fuel filler caps	24.11.96				X	X	X	X							
1078-64/2		Exchange of the elevator hinges	08.04.97				X	X	X	X							
1078-65		Modification of left and right rudder pedal unit	12.12.96				X	X	X	X							
1078-66		Weights and residual moments of control surfaces	10.02.97				X	X	X	X							
1078-67		Weights and residual moments of control surfaces	10.02.97				X	X	X	X							


X = applicable

Doc. No.: 115.TM.001		Grob Aircraft AG																
Chapter: 2		Service Bulletins												Status: 09. May 2012				
Type: G 115		(issued / in preparation)																
LBA-TCDS No.: 1078																		
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks		
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA					
1078-68		Modification of the flap control	29.04.97	X	X	X												
1078-69		Cancellation of the reduction of the never exceed speed	10.07.97				X	X	X	X								
1078-70		Installation of a 3-blade constant speed propeller	21.10.97							X								
1078-71		Installation of a modified air filter box	27.10.97				X	X	X	X								
1078-72		Installation of a modified muffler attachment bracket	04.02.98				X	X	X	X								
1078-73		Securing of the lower rudder bolt	12.11.97	X	X	X	X	X	X	X								
1078-74		Revision of the Flight Manual	15.09.98				X	X	X	X								
1078-75		Inspection of the trim tab hinges	15.05.98	X	X	X	X	X	X	X								
1078-76		Exchange of an oil hose	14.09.98				X	X	X	X								
1078-77		Installation of a 2-piece horizontal stabilizer	05.12.98				X	X	X	X								
1078-78/2		Exchange of the propeller attachment bolts	20.08.99							X								
1078-79		Revision of the Flight Manual	30.07.99								X							
1078-80		Various modifications	02.09.99								X							
1078-81		Various modifications	23.09.99								X							
1078-82		Fuel tank access panel leakage	04.10.99								X							
1078-83		Revision of the Flight Manual	13.12.99								X							
1078-84		Various modifications	30.11.99								X							
1078-85		Modification of the trim control	23.11.99				X	X	X	X								
1078-86		Installation of an additional anti-icing protection	10.11.99						X	X								
1078-87		Modification to the G 115D standard	17.11.99				X	X	X	X								
1078-89		Modification of the wiring between battery and starter	21.01.00								X							
1078-90		Installation of dripping protectors	21.01.00								X							
1078-91/2		Installation of maintenance free hoses	07.02.01	X	X	X												
1078-96		Horizontal Stabilizer	13.12.01				X		X									
1078-98		Introduction of an UHF-Transmission Placard	29.08.00								X							
1078-101		Installation of an additional anti-icing protection	10.11.00								X							
1078-103	IM115-84	Baggage compartment cover	03.10.01						X		X	X						
1078-105	OÄM1078-44	4000 hours inspection G 115C/D	22.06.04				X	X	X	X								
1078-106		Replacement of Coupling Magneto by Retarder Sys.	25.04.01								X							
1078-107	OÄM1078-23	IFR operation	08.05.02								X							
1078-108	IM115-88	Canopy jettison	27.02.02									X						
MSB1078-109	IM115EG-E30	Replacement of 2 Relays	12.09.01									X						


X = applicable

Doc. No.: 115.TM.001		Grob Aircraft AG														
Chapter: 2		Service Bulletins												Status: 09. May 2012		
Type: G 115		(issued / in preparation)														
LBA-TCDS No.: 1078																
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA			
MSB1078-110/1	MÄM1078-25	Modification fuel system	13.12.01									X	X			
OSB1078-111	IM115-87	Baggage Compartment Cover	12.09.01									X				
OSB1078-112/2	IM115-90	Exhaust muffler installation	15.05.03				X	X	X	X	X	X	X			
OSB1078-113	MÄM1078-26	Alternative air filter	17.09.01									X	X			
MSB1078-114	MÄM1078-28	Avionic Rack Installation	24.09.01									X				
OSB1078-115/2	OÄM1078-29	Fuel tank sealant	21.03.01				X	X	X	X	X	X	X			
OSB1078-116	OÄM1078-32	Instrument panel clearance	12.11.01									X				
OSB1078-117/2	OÄM1078-29	Fuel quantity probe	31.07.02									X	X			
OSB1078-118	OÄM1078-30	Trim drive unit	20.11.01									X	X			
OSB1078-119	OÄM1078-31	Mic/ tel lead	23.11.01									X				
MSB1078-120/5	N/A	Brake Master Cylinder	16.01.09									X				
MSB1078-121		Main Gear Door Actuator	25.02.02											X		
MSB1078-122/7	MÄM1078-33	Hinge Bracket	27.03.09									X				Supersedes 1078-122/4 & 5
OSB1078-124	OÄM1078-36	Manifold pressure indication	12.09.02									X				
MSB1078-126/1	MÄM1078-38	CO in cockpit	07.10.02	X	X	X										Supersedes MSB1078-126
OSB1078-127		Engine cooling air baffles	25.07.02									X				
OSB1078-128		Landing Gear Limits	14.06.02										X			
OSB1078-129	OÄM1078-39	Hard Landing Indicator	19.06.02										X			
OSB1078-131	OÄM1078-41	Fuel Pressure Transmitter	09.08.02									X	X			
MSB1078-132/1	OÄM1078-40	Oil Pressure Transmitter	23.09.02									X	X			
OSB1078-133		Alternative Seat Harness	31.07.02	X	X	X	X									
MSB1078-134		Elevator Trim	15.10.02									X				
MSB1078-135	MÄM1078-39	Exchange of the Low Fuel Sensor Circuit Breaker	27.09.02									X	X			
OSB1078-136	IM115-90	Exchange of the Air Condition Service Adaptors	19.11.02											X	X	
MSB1078-137	MÄM1078-40	Fuel line fixation	10.02.03									X	X			X
OSB1078-140	OÄM1078-42	Canopy handle cover, various canopy modifications	21.03.03									X	X			X
OSB1078-140/1	OÄM1078-53	Canopy handle cover	22.09.05									X	X			X
OSB1078-141	OÄM1078-43	Modification of the engine fire extinguisher	08.04.03									X				X
MSB1078-142/3		Aircraft documentation status G115, G115A	20.01.12	X	X											Supersedes MSB1078-142/2
MSB1078-143/3		Aircraft documentation status G115B	20.01.12			X										Supersedes MSB1078-143/2
MSB1078-144/8		Aircraft documentation status G115C, G115D	20.01.12				X	X	X	X						Supersedes MSB1078-144/7
MSB1078-145/19	MÄM1078-151	Aircraft documentation status G115E	29.07.11									X				Supersedes MSB1078-145/18

X = applicable

Doc. No.: 115.TM.001		Grob Aircraft AG															
Chapter: 2		Service Bulletins											Status: 09. May 2012				
Type: G 115		(issued / in preparation)															
LBA-TCDS No.: 1078																	
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks	
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA				
MSB1078-146/9		Aircraft documentation status G115EG	09.05.12											X			Supersedes MSB1078-146/8
MSB1078-147/7		Aircraft documentation status G115TA	20.12.11												X		Supersedes MSB1078-147/6
OSB1078-148/1	IM115EG-E31	Alternative ignition switch	19.06.09											X		X	
OSB1078-149		Manifold Pressure Indicator	27.05.04											X		X	
OSB1078-150	OÄM1078-047	Mixture Lean Stop Device	28.09.04											X		X	
MSB1078-151/2		Hoffmann Propeller	14.07.04				X	X	X	X	X						Supersedes MSB1078-151/1
MSB1078-152		Inspection of Fuel Hoses / Überprüfung von Benzinschläuchen	01.10.04	X	X												
MSB1078-153	MÄM1078-48	Exchange of the Main Landing Gear Swivel Bearing	22.11.04												X	X	
OSB1078-154	OÄM1078-52	Mode-S Transponder	01.12.06											X		X	
MSB1078-156	MÄM1078-58	Slick Start Booster	06.12.06											X		X	
MSB1078-157	MÄM1078-062	Rudder Support Assy	23.01.08											X	X	X	
OSB1078-158	OÄM1078-064	Alternate ELT	22.09.08											X		X	
OSB1078-159	OÄM1078-063	Alternate Brake Cylinder	27.05.08	X	X	X		X	X	X	X	X	X	X	X	X	
OSB1078-160		Aerobatic Colour Scheme	10.06.08											X		X	
MSB1078-161/1	MÄM1078-150	Service Life Extension	11.05.12	X	X	X	X	X							X		Supersedes MSB1078-161
OSB1078-162	MÄM1078-075	Securing of MLG Bolts	10.07.09				X	X	X	X	X	X	X			X	
MSB1078-163/2		Wing shear bolt torque	30.09.10				X	X	X	X	X	X	X				Supersedes MSB1078-163/1
MSB1078-164		Canopy jettison	22.07.09				X	X	X	X	X	X					
MSB1078-165		Nose wheel fork	03.11.09				X	X	X	X	X	X					
MSB1078-166		Chafing protection	11.09.09											X			
MSB1078-167	MÄM1078-107	Canopy jettison	19.11.09											X			
MSB1078-168		Airfilterbox inspection	12.11.09	X	X	X	X	X	X	X	X	X	X				
MSB1078-169		Inspection of the canopy lock	27.11.09				X	X	X	X	X	X	X				
MSB1078-170		Inspection of the flap operating lever	03.12.09	X		X											
MSB1078-171		Inspection of start relay	07.12.09											X		X	
MSB1078-172/1		Wing shear bolt torque	22.09.10											X	X		Supersedes MSB1078-172
MSB1078-173/1		Inspection and exchange of Oil Dip Stick	18.05.10											X			
OSB1078-174	OÄM1078-127	Marking of Canopy Jettison Handle	27.07.10				X	X	X	X	X	X	X		X		
RSB1078-175		Exchange of Integrated Engine Instrument	02.07.10											X			
RSB1078-177	MÄM1078-126	Canopy rear attachment	15.10.10											X	X		
OSB1078-178/5	OÄM1078-129	Optional installation of a Traffic Advisory System	17.02.11											X			Supersedes OSB1078-178/4
RSB1078-180/1	MÄM1078-135	Improved Attachment of shimmy damper	19.09.11											X	X		Supersedes RSB1078-180

X = applicable

Doc. No.: 115.TM.001		Grob Aircraft AG															
Chapter: 2																	
Type: G 115																	
LBA-TCDS No.: 1078		Service Bulletins (issued / in preparation)											Status: 09. May 2012				
SB-No.	ÄM No.	Subject	Date of issue											Major Change	Minor Change	Remarks	
				G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA				
MSB1078-181	MÄM1078-142	Instrument panel clearance	18.04.11									X					
RSB1078-182	MÄM1078-148	Improved Canopy Lock	25.11.11						X	X	X	X	X			X	
OSB1078-183	MÄM1078-151	Alternative Accelerometer FALCON	29.07.11								X	X				X	
OSB1078-184	MÄM1078-153	Alternative Toggle switch	14.02.12	X	X	X	X	X	X	X	X	X	X			X	
MSB1078-185		Inspection of Brake Torque plate	11.11.11											X			
MSB1078-186/2	MÄM1078-161	Inspection of trim tab arm	29.03.12								X	X					Supersedes MSB1078-186/1
MSB1078-187		Inspection of NLG	20.04.12											X			

X = applicable